CSI Country Wide Case Study Safety Strategy Discussion

Construction Safety Investigator

Instructions

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions should not be limited to the subject above and should pertain to the activities that workers will be involved in that may have the potential for safety related exposures.

Case Day:

June 24, 2002

Accident Type:

Equipment Maintenance - Caught Between Accident

Relevant laws, rules and codes may include:

29 CFR 1926.21 (b)(2), Equipment Operator's Manual

Case:

A 21 year-old dump-truck driver died after being caught between the frame and dump body of an off-road dump truck while performing routine lubrication.

Accident Detail:

The site of the incident was a landfill where a new cell for refuse disposal was being constructed by an excavation company. Five drivers, including the victim, were assigned to operate off-road trucks and spent the day of the incident hauling earth from the excavation site to another area of the landfill.

Near the end of the shift, the victim and two other dump-truck operators drove to the service area to grease their trucks as the excavator operator was not yet ready to load their trucks. After the victim's coworkers finished lubricating their trucks, they drove their trucks out of the service area.

When the foreman had finished (approximately 7 p.m.), he drove and encountered a truck in the service area. Stopping to investigate, he discovered its engine running and heard the air compressor but did not hear the usual clicking sounds of the grease gun. He found the victim caught face down between the truck frame and dump body near a grease fitting located toward the cab end of the frame.

Reconstructive Safety Evaluation:

- What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?



Accident Scene Conclusion:

The evidence suggested that the victim had raised the dump body, exited the truck with the engine running, and entered the space between the dump body and frame to lubricate the suspension system and drive shaft.

He did this without first placing the tipping control lever in the hold position and securing the locking clamp, and without manually securing the dump body lock at the rear of the truck.

The dump body lock was not secured, and therefore, there was nothing to keep the dump body in the raised position should the tipping control lever become dislodged for any reason.

Preventive Safety Measures Include:

- Ensure that raised dump bodies are blocked against inadvertent lowering before employees work under them.
- Periodic inspections should be conducted by supervisors to ensure worker compliance with these safety measures.
- Develop, implement, and enforce a comprehensive written safety program for all workers which includes training in the recognition and avoidance of unsafe conditions and required safe work practices that apply to their work environments.

Attendance Roster		

Reference: This case was reported in the NIOSH Fatality Assessment and Control Evaluation (FACE) Program, Report # 2002-08.

Chubb. Insured.[™]

Chubb is the marketing name used to refer to subsidiaries of Chubb Limited, providing insurance and related services. For a list of these subsidiaries, please visit our website, www.chubb.com. Insurance is provided by ACE American Insurance Company and its U.S. based Chubb underwriting company affiliates. All products may not be available in all states. This communication contains product summaries only. Coverage is subject to the language of the policies as actually issued. Surplus lines insurance is sold only through licensed surplus lines producers. Loss control evaluations, reports, recommendations and services are made solely to assist the insurer in underwriting and loss control and are not to be construed as an added benefit for the insured, property owner or any other party (this may not apply if loss control services are purchased separately and specifically pursuant to a service agreement). Evaluation for any hazard or condition does not imply that it is covered under any policy. Chubb is the world's largest publicly traded property and casualty insurance group. With operations in 54 countries, Chubb provides commercial and personal property and casualty insurance, personal accident and supplemental health insurance, reinsurance and life insurance to a diverse group of clients. Chubb Limited, the parent company of Chubb, is listed on the New York Stock Exchange (NYSE: CB) and is a component of the S&P 500 index.

Copyright ©2016 04/2016