# Downstream Energy Reduced Personnel Availability Guidance

**Energy Risk Engineering** 

CHUBB



Operation, maintenance, inspection and emergency response protocols or contingency plans may assume response from key individuals, teams or specialist contractors.

The Coronavirus pandemic may result in reduced personnel availability due to social isolation protocols, illness or care commitments. Reduced personnel availability may result in enhanced risk to operations, inability to maintain normal activities, delay in restarting operations or ineffective response to subsequent incidents.

It is recommended that clients review existing procedures and service arrangements to identify potential reduced personnel exposures. Where possible risk assessment to develop mitigation plans for reduced personnel availability should be implemented.

### Managing the risks

It is recognized that personnel availability will vary as the situation develops.

The following are recommended to be considered in reduced personnel planning:

- Shift teams of adequate size and competence
- Site security and emergency response
- Contingency plans, including key/specialist personnel exposures
- Safety Critical Equipment inspection and maintenance
- Critical maintenance, mechanical integrity inspections and contract services
- Statutory maintenance and turnarounds

Reduced personnel availability may expose safe operations, delay business restart or impair emergency response

## Operation, Inspection and Maintenance

- Evaluate minimum shift staffing for safe operations.
- Evaluate capability and resilience available for safety critical equipment maintenance, testing and inspections.
- Review the resilience of contract service providers including their contingency planning. Sole providers of specialist capabilities should be specifically identified.
- Review requirements for statutory maintenance and mechanical integrity inspection (e.g. pipework, pressure vessels, heaters, pressure relief devices, rotating machinery etc.).
- Risk assess and document any deferral ensuring mitigations are in place.

## Response Planning

- Document requirements for minimum staffing for shift operations, maintenance, inspection, technical management for continued production and define staffing thresholds for suspending production.
- Define staffing levels for temporary shutdowns and mothballed status and restarting operations. The LMA 9142 Mothballing and Recommissioning Questionnaire is referenced for guidance.
- Ensure that emergency response plans are resilient to reduced personnel availability.
- Identify key staff exposures, including IT staff responsible for supporting remote working.

#### **Risk Management Protocols**

- Key staff resilience plans should be reviewed and, if needed, additional socially isolated back-ups identified. Define staffing thresholds for suspending production.
- Protective systems should continue to be fully functional. Maintenance of protective equipment should only be conducted by appropriately qualified specialists. Where specialist capability is scarce, critical maintenance should be prioritized based upon documented risk assessment (e.g. emergency shutdown equipment over internal metering).
- Where services are supported by sole contractors the availability of alternative providers should be established or the contingency plans of the sole contractors approved.

- Routine maintenance should consider the possibility of prolonged shutdown and the requirements for recommissioning.
- Contingency options for deferred statutory maintenance should be reviewed with the relevant regulating authority, certifying body and/or insurer.
- Additional keyholders or call-out responders should be identified and trained.
- Emergency response, contingency and business continuity plans should have alternate staff designated and trained for all key roles. It is recommended that as far as possible alternate staff are isolated from each other.
- Ensure plans are resilient to changes of occupancy, prolonged outage and recommissioning requirements.

#### **Further Guidance**

- Assessing the Safety of staffing arrangements for process operations in the chemical and allied industries (HSE 348/2001)
- Pandemic Planning guide API Guidance Document 1180

#### **Contact Us**

For more information about protecting your business, contact your local risk engineer:

Chubb Global Markets & Continental Europe - <u>Ian.taylor@chubb.com</u>

Eurasia & Africa - gyula.kiss@chubb.com

Asia Pacific - wim.matthys@chubb.com

Latin America – jose.alencar@chubb.com or AndresCamilo.Forero@Chubb.com

Chubb. Insured.<sup>™</sup>

This document is not intended to identify all hazards that may exist, nor is it intended to be an exhaustive review of all possibilities or eventualities and is purely advisory and should be used only in association with Chubb Energy Underwriting and Engineering in respect of a proposed or existing insurance policy. The decision and responsibility for implementation of any guidance within this document rests with the recipient's management and / or the controllers of the facilities, plant and equipment that is the subject of this document. This document does not guarantee, assure or warrant in any way that the recipient is in compliance with instead is contents will eliminate all hazards or accidents. It is a condition of delivery of this document (whether under contract or otherwise) that Chubb shall not be held liable for any loss or damage arising out of or in connection with the data, calculations or opinions expressed herein.

All content in this material is for general information purposes only. It does not constitute personal advice or a recommendation to any individual or business of any product or service. Please refer to the policy documentation issued for full terms and conditions of coverage.

Chubb European Group SE (CEG) is an undertaking governed by the provisions of the French insurance code with registration number 450 327 374 RCS Nanterre. Registered office: La Tour Carpe Diem, 31 Place des Corolles, Esplanade Nord, 92400 Courbevoie, France. CEG has fully paid share capital of c896,176,662. UK business address: so Leadenhall Street, London EG3A 3BP. Authorised and supervised by the French Prudential Supervision and Resolution Authority (4, Place de Budapest, CS 92459, 75436 PARIS CEDEX 09) and authorised and subject to limited regulation by the Financial Conduct Authority. Details about the extent of our regulation by the Financial Conduct Authority are available from us on request.